REPORT OF CHANNEL CONDITIONS (FOR CHANNELS 400 FEET WIDE OR GREATER) (ER 1130-2-316)							Page 1 of 1 May-2008		
NAME OF CHANNEL	Date	AUTHORIZED PROJECT Left			Left	Right	Right		
	of Survey	Width	Length	Depth		Inside Quarter	Inside Quarter	Outside Quarter	
		(feet)	(miles)	(feet)	(feet)	(feet)	(feet)	(feet)	
Entrance Channel: from 1,600 feet seaward of red Buoy-2 to 400 feet seaward of green Buoy-3	May-2008	400	0.4	35	34.9	36.9	37.2	38.2	
Entrance Channel: from 400 feet seaward of green Buoy-3 to 350 feet landward of red Buoy-6 at intersection of Entrance Channel & Cut-1	May-2008	400	0.7	35	34.3(2)	37.6	39.0	37.2	
Cut-1: from 350 feet landward of red Buoy-6 to green Light-9 at intersection of Cuts-1 & 2	May-2008	300	0.1	33	32.9	34.9	35.5	36.3	
Cut-2: from green Light-9 to green Light-11 at intersection of Cut-2 & Turning Basin	May-2008	300/480	0.2	33	37.0	37.0	35.7	36.6	
Turning Basin	May-2008	1400x1200	0.3	33	32.2(3)	32.4(3)	35.5	33.4	
North Turning Basin Extension	May-2008	950x650	0.1	24	23.0	21.1	23.9	27.1	

Remarks:

Survey #08-132

- 1. Spot shoals on outer edge of channel.
- 2. Spot shoals on outer edge of channel.
- 3. Spot shoal on outer edge of channel.
- 3. Spot shoals sporatic in turning basin.
- 4. Significant shoals in northeast quadrant.